## **EAST Search History**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1	"20030064757"	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 08:47
L2	0	1 and satellite	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 08:48
L3	3	display\$4 near9 ((recept\$4 receiv\$3 sensitivity meter rssi signal adj2 strengh) adj2 level) same bluetooth	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 10:03
L4	0	display\$4 near9 ((recept\$4 receiv\$3 sensitivity meter rssi signal adj2 strengh) adj2 level) near4 bluetooth	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 10:04
L5	1	(display\$4 indicat\$4) near9 ((recept\$4 receiv\$3 sensitivity meter rssi signal adj2 strengh) adj2 level) near4 bluetooth	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 10:05
L6		(display\$4 indicat\$4) near9 ((recept\$4 receiv\$3 sensitivity meter rssi signal adj2 strengh) adj2 level) with bluetooth	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 10:05
L7	4	(display\$4 indicat\$4) near9 ((recept\$4 receiv\$3 sensitivity meter rssi signal adj2 strengh) adj2 level) same bluetooth	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 10:05
L8	109	(display\$4 indicat\$4) near9 ((recept\$4 receiv\$3 sensitivity meter rssi signal adj2 strengh) adj2 level) and bluetooth	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 10:21
L9	73	8 and (@ad<="20030103" @rlad<="20030103" @prad<="20030103")	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 10:23
L10	23	(display\$4) near9 ((recept\$4 receiv\$3 sensitivity meter rssi signal adj2 strengh) adj2 level) near8 satellite	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 12:42
L11	22	10 and (@ad<="20030103" @rlad<="20030103" @prad<="20030103")	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 10:26
L12	158	(display\$4) near9 number near8 satellite	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 13:49
L13	131	12 and (@ad<="20030103" @rlad<="20030103" @prad<="20030103")	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 10:26

## **EAST Search History**

L14	5	(display\$4) near9 (sensitivity meter rssi signal adj2 strengh) near8 bluetooth	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 12:46
L15	11	(display\$4) near9 (sensitivity meter rssi signal adj2 strengh) same bluetooth	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 13:50
L16	250	(sensitivity meter rssi signal adj2 strengh) near4 bluetooth	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 12:50
L17	15	16 same (display\$3)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 12:50
L18	6	("3972320"   "4827943"   "4865044"   "5757916"   "5969670"   "6055426").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/08/28 13:45
L19	57	lowrance.as.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 13:49
L20	22814	(display\$4) near9 (sensitivity meter rssi signal adj2 strengh)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 13:50
L21	0	19 and 20	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 13:50
L22	777918	(sensitivity meter rssi signal adj2 strengh)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 13:50
L23	10	19 and 22	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/08/28 13:50

8/28/06 2:32:55 PM C:\Documents and Settings\TPham13\My Documents\EAST\Workspaces\10748901.wsp Page 2